Q-300

SVE BULLETIN

SPECIAL VEHICLE ENGINEERING – BODY BUILDERS ADVISORY SERVICE

E-Mail via Website: www.FordBBAS.com (click "Contact Us")

Toll-free: (877) 840-4338

QVM Bulletin: Q-300 Date: 23, Jan 2020

NVH Cover Over PTO Opening 10R Transmission Super Duty Chassis Cab

Models Affected: 2020 Model Year Ford Super Duty Vehicles

Description:

This bulletin is to address 2020 Model Year Ford Super Duty Chassis Cab equipped with a transmission NVH cover which may interfere with PTO installation. The recommended solution is to cut away a portion of the NVH cover to provide clearance for PTO device installation. It is important to cut away portion of the NVH cover, shown in the images below. Please make sure that the lower attachment point is left intact to still secure the remaining portion of NVH cover to transmission, reference images below. ***EXCERCISE CAUTION WHEN REMOVING COVER – AVOID ANY DAMAGE OR SEVERING OF TRANSMISSION, WIRING AND/OR FLUID LINES.***



Refer to the Body Builder Layout Book for additional guidelines and recommendations. If you have any questions, please contact the Ford Truck Body Builders Advisory Service as shown in the header of this bulletin.